

**IEPA - DIVISION OF WATER POLLUTION CONTROL
DIGITAL PHOTO REPORT**

Date: 5-31-18	Site Name: <small>Ex. 6 (Personal Privacy)</small> Family Farms
Photo By: Lee Heeren	
County: Jo Daviess	
Comments: A view of a tractor-tank wagon positioned at the feedlot runoff-containment area upon arriving at the facility. View is west.	
Photo #: 1	
Photo Title: 053118 <small>Ex. 6 (Personal Privacy)</small> LH(2)	

Date: 5-31-18	Site Name: <small>Ex. 6 (Personal Privacy)</small> Family Farms
Photo By: Lee Heeren	
County: Jo Daviess	
Comments: A view looking downhill toward Welch Road. View is south.	
Photo#: 2	
Photo Title: 053118 <small>Ex. 6 (Personal Privacy)</small> LH(3)	

**IEPA - DIVISION OF WATER POLLUTION CONTROL
DIGITAL PHOTO REPORT**

Date: 5-31-18	Site Name: Ex. 6 (Personal Privacy) Family Farms
Photo By: Lee Heeren	
County: Jo Daviess	
Comments: Another view of the drainage.	
Photo #: 3	
Photo Title: 053118 Ex. 6 (Personal Privacy) LH(4)	


Date: 5-31-18	Site Name: Ex. 6 (Personal Privacy) Family Farms
Photo By: Lee Heeren	
County: Jo Daviess	
Comments: A close-up of the manure in the drainage pathway. View is looking north.	
Photo #: 4	
Photo Title: 053118 Ex. 6 (Personal Privacy) LH(5)	

**IEPA - DIVISION OF WATER POLLUTION CONTROL
DIGITAL PHOTO REPORT**

Date: 5-31-18	Site Name: <small>Ex. 6 (Personal Privacy)</small> Family Farms
Photo By: Lee Heeren	
County: Jo Daviess	
Comments: A view of the lower end of the drainage leading into the road ditch. Notice this area had been mowed before the latest rain event. A culvert is located under the gravel road leading to a grazing pasture. View is southwest.	
Photo #: 5	
Photo Title: 053118 <small>Ex. 6 (Personal Privacy)</small> LH(6)	

Date: 5-31-18	Site Name: <small>Ex. 6 (Personal Privacy)</small> Family Farms
Photo By: Lee Heeren	
County: Jo Daviess	
Comments: A close-up of the wastewater in the road ditch. View is southwest.	
Photo#: 6	
Photo Title: 053118 <small>Ex. 6 (Personal Privacy)</small> LH(7)	

**IEPA - DIVISION OF WATER POLLUTION CONTROL
DIGITAL PHOTO REPORT**

Date: 5-31-18	Site Name: Ex. 6 (Personal Privacy) Family Farms
Photo By: Lee Heeren	
County: Jo Daviess	
Comments: A view of facility personnel pumping the wastewater into the tank wagon.	
Photo #: 7	
Photo Title: 053118 Ex. 6 (Personal Privacy) LH(8)	

Date: 5-31-18	Site Name: Ex. 6 (Personal Privacy) Family Farms
Photo By: Lee Heeren	
County: Jo Daviess	
Comments: Feedlot wastewater runoff exits this load ramp and into the small containment area. Wastewater is pumped into the application tank wagon. Resulting manure solids are removed by a skid loader and land applied. View is north.	
Photo#: 8	
Photo Title: 053118 Ex. 6 (Personal Privacy) LH(9)	

**IEPA - DIVISION OF WATER POLLUTION CONTROL
DIGITAL PHOTO REPORT**

Date: 5-31-18	Site Name: <small>§ 87(2)(b) (Personal Privacy)</small> Family Farms
Photo By: Lee Heeren	
County: Jo Daviess	
Comments: This is a partial view of the upper feedlot area. Notice the amount of roof water and surface area that collects storm water that co-mingles with livestock manure. View is north.	
Photo #: 9	
Photo Title: 053118 <small>§ 87(2)(b) (Personal Privacy)</small> LH(10)	